

Parts Price List

DC-501 Double Check Valve Backflow Preventer 1 1/4", 1 1/2", 2"

2017

Catalogue	Description	No. refer to drawing	Price
0465-0502	Cover Assembly	1	\$52.00
0266-3102AN	Retainer	3	\$9.00
0465-27602-IN	Inlet Check Valve Assembly	2	\$45.00
0466-027602-OUT	Outlet Check Valve Assembly	4	\$45.00
0310-7314BPM-14NTFBA	Test Cock 1/4" BSP	10	\$15.00
0466-9902	Clamp Assembly	7	\$21.00
0466-48112NT	Adaptor Assembly NPT 1 1/2"	6, 9	\$19.50
0466-48114NT	Adaptor Assembly NPT 1 1/4"	6, 9	\$19.50
0466-4802NT	Adaptor Assembly NPT 2"	6, 9	\$19.50
0465-5699-02-CRK	Complete Rubber Repair Kit		\$34.00



DC-501

DC-501 Double Check Valve Backflow Preventer 1 ¼", 1 ½", 2"

Parts Exploded View

No. Part Description

1. Cover Assembly
2. Inlet Check Valve Assembly #1
3. Retainer
4. Outlet Check Valve Assembly #2
5. Cover Seal
6. Inlet Shut-Off Valve
7. Clamp Assembly
8. Body Assembly
9. Outlet Shut-Off Valve
10. Test Cocks



A.R.I. FLOW CONTROL ACCESSORIES Ltd.
www.arivalves.com avner@ari.co.il Tel: 858-2328279



USA Distributor Tel: (954) 980-9850 Email: cjhart@ubsbackflow.com

LIST DC-501